


CNC Cable

AdvanceCut 75
AdvanceCut 125



** Important –

Ensure all remaining non connected spade terminals of the cable are individually insulated with heat shrink or electrical tape.



Pin Configuration

14 Pin Round	Function	Wire Colour	Fork Terminal
8	Start	Yellow	FT1
9	Start	Green	FT2
7	Divided Voltage (-)	Black	FT3
6	Divided Voltage (+)	Red	FT4
13	Transfer	Blue	FT7
14	Transfer	White	FT5